

Unique ID	Town/Village	Road	Location	Sign Type	Sign Face	Does sign include additional information	Power	Easting	Northing	Owner
29	Ashwell	Oakham Rd	adj Water Lane	SID	SID	SLOWDOWN/THAN K YOU	Electric	486625	313451	RCC
205	Braunston	Knossington Rd	estbnd entrance	VAS	30	SLOW DOWN	Solar	482963	306757	RCC
509	Edith Weston	Manton Rd	jct King Edwards Way	VAS	30			492192	305124	RCC
510	Edith Weston	Manton Rd	jct Weston Rd	VAS	30			492714	305131	RCC
1060	Ketton	A6121	estbnd adj Chater Cl	VAS	30	SLOW DOWN	Electric	498664	305184	RCC
1171	Langham	A606	sthbnd entrance	SID	SID	SLOWDOWN/THAN K YOU	Electric	483966	311134	RCC
1144	Langham	Cold Overton Rd	estbnd entrance	SID	SID	SLOWDOWN/THAN K YOU	Electric	483940	310790	RCC
38	Manton	A6003	manton top	VAS	40					RCC
39	Manton	A6003	manton top	VAS	40					RCC
40	Manton	C8326	westbound approach	SID	SID					RCC
42	Oakham	Burley Road	adj school	SID	SID		Electric			RCC
3530	Ryhall	A6121	nthbnd entrnce	SID	SID	SLOWDOWN/THAN K YOU	Electric	503450	309982	RCC
3379	Ryhall	A6121	sthbnd entrance	SID	SID	SLOWDOWN/THAN K YOU	Electric	503764	311560	RCC
4241	Uppingham	A6003	nth bnd entrance	SID	SID	SLOWDOWN/THAN K YOU	Electric	486665	299028	RCC
4682	Whitwell	A606	estbnd entrance	SID	SID	SLOWDOWN/THAN K YOU	Solar			RCC
4683	Whitwell	A606	opp BullBrigg Lane	VAS	30	SLOW DOWN	Electric			RCC
4667	Preston	A6003	southbound entrance	SID	SID	SLOWDOWN/THAN K YOU	Solar			RCC
4664	Little Casterton	G9301	estbnd entrance	SID	SID	SLOWDOWN/THAN K YOU	Solar			RCC
22	Great Casteron	B1081	nthbnd entrance	SID	SID				PARISH	UNIPAR
23	Great Casteron	B1081	sthbnd entranc	SID	SID				PARISH	UNIPAR

Manufacturer	Date Installed	Warranty Date end	Maintained Date	Insp Date	Is device on classified road	Speed of Road	Date of speed survey	Average Speed	85th Percentile	accidents in last 5 years	located at village entrance
UNIPART DORMAN				04/06/21	No	30					Yes
DAMBACH				04/06/21	No	30					Yes
DAMBACH				04/06/21							
DAMBACH				04/06/21							
UNIPART				04/06/21	Yes - A6121	30					Yes
UNIPART DORMAN				04/06/21	Yes - A606	30					Yes
UNIPART DORMAN				04/06/21	No	30					Yes
COEVAL	Sep-16			04/06/21							
COEVAL	Sep-16			04/06/21							
DAMBACH				04/06/21							
UNIPART				04/06/21							
UNIPART DORMAN				04/06/21	Yes - A6121	30					Yes
UNIPART DORMAN				04/06/21	Yes - A6121	30					Yes
UNIPART DORMAN				04/06/21	Yes - A6003	30					Yes
UNIPART DORMAN				04/06/21	Yes - A606	30					Yes
DAMBACH				04/06/21	Yes - A606	30					Yes
WESTCOTEC	03/09/14			04/06/21	Yes - A6003	30	-	-	-		Yes
UNIPART DORMAN				04/06/21	No	30					Yes
T DORMAN			Sep-19	Not all lights	Fixed	29/10/19		07/08/20	OK		
T DORMAN			Sep-19	Not working	Fixed	29/10/19		07/08/20	OK		

SID located Near By	if Yes how far?	Facilities within area	Does Device have any faults	Does SID record speed data	obstructed by vegetation	If yes can it be cut back	If no can the device be repositioned
No		N/a	Some lights not working	No	No		
No		N/a	Not operational	No	Yes	No	Yes
No		N/a	Some lights not working	No	No		
No		N/a	Some lights not working	No	No		
No		N/a	Some lights not working	No	No		
No		N/A	Some lights not working	No	No		
No		N/A	Some lights not working	No	No		
No		N/A	Some lights not working				
Yes	50-100m	N/a	Some lights not working	No	No		
Yes	50-100m	N/a	Not operational	No	Yes	Yes	
No		N/A	Some lights not working	No	No		
No		N/A	Held together with tape	No	No		

Notes	Insp Date	Notes
Letter 'SPEED' not all working		
Not working		
Not working		
Doesn't turn off		
Slow only half working		
Not working		
Not working		
Not working		
Constantly Flashing		
Not working		
Not Opeational		
Slow down does not flash		
Not working		
Not working		
Not working		
Not working		
Not working		